

単3バッテリーパックF<sub>G</sub>は、MZ-5、MZ-10、MZ-50 および MZ-3 カメラに単3 乾電池を使用するための専用アクセサリです。

This AA-Battery Pack F<sub>G</sub> is designed for use with the MZ-5/ZX-5, MZ-10/ZX-10 and MZ-50/ZX-50 cameras which allows you to use AA size batteries for the camera's power source.

### Notes :


- A camera case will not fit if the AA-Battery Pack F<sub>G</sub> is attached to the camera.
- Do not apply an excessive force to the battery chamber cover on the camera when the battery grip is attached.
- The Battery Pack can be mounted on a tripod.
- Use only four 1.5V AA size alkaline batteries. Any other type of batteries such as Ni-Cd and manganese batteries cannot be used.

この製品の安全性については十分注意を払っておりますが、下記マークの内容については特に注意をしてお使いください。


### 注意


このマークの内容を守らなかった場合、使用者が軽傷または中程度の傷害を受けたり、物的損害の可能性のあることを示すマークです。


 は、禁止事項を表わすマークです。

 は、注意を促すためのマークです。

### 注意

 電池をショートさせたり、火の中に入れないでください。また、分解や充電をしないでください。破裂・発火の恐れがあります。

 電池は+の向きを逆にしないでください。向きを間違えると、液漏れ、発熱、破裂の恐れがあります。

 万一、内部の電池が発熱・発煙を起こしたときは、速やかに電池を取り出してください。この場合、やけどに十分ご注意ください。

Although we have carefully designed this product for safe operation, please be sure to follow the precautions given below.

### CAUTION


This mark indicates precautions that, if not followed, could result in minor or medium injury to the operator or damage to the equipment.

### CAUTION

- Never try to disassemble, short or re-charge the battery. Also, do not dispose of the battery in fire, as it may explode.
- Remove the batteries if they become hot or begin to smoke. Be careful not to burn yourself during removal.
- Misuse of batteries can cause hazards such as leakage, overheating, explosions, etc.


The battery should be inserted with the "+" and "-" sides facing correctly.

1




1. 電池ぶた開放レバーを矢印の方向に引いて、電池ぶたを開けます。
2. 電池マークに合わせて、単3乾電池4個を正しく入れ、電池ぶたを閉めます。
3. カメラの電池ぶたを開け、リチウム電池を取り出します。

2




3




1. Open the battery chamber cover by sliding the opening lever in the direction of the arrow.
2. Insert four AA size batteries into the battery chamber in accordance with the diagram located in the battery chamber.
3. Remove the lithium batteries from the camera.

4



5



4. カメラの電池ぶたが図のように単3バッテリーパックF<sub>6</sub>の溝に入るようにして単3バッテリーパックF<sub>6</sub>をカメラに差し込み、取り付けねじ部とカメラの三脚ねじ穴を合わせます。
5. 着脱ダイヤルを図の方向に回して固定します。

4. To attach the AA-Battery Pack F<sub>6</sub> to the camera, first insert the battery cover into the slot on the AA-Battery Pack F<sub>6</sub> and then align the attachment screw and the guide column on the Battery Pack with the tripod socket and the hole at the base of the camera.
5. Secure the battery pack to the camera by turning the attachment wheel in the direction of the arrow.





Asahi Optical Co., Ltd. 1-1, Naga-ohji 1-chome, Chiyoda-ku, Tokyo 100, JAPAN  
 Pentax Europe n.v. Weyveldlaan 3-5, 1930 Zaventem, BELGIUM  
 Pentax GmbH, Julius-Vosseler-Strasse, 104, D-22527 Hamburg, GERMANY  
 Pentax U.K. Limited Pentax House, Heron Drive, Langley, Slough SL3 8PN, U.K.  
 Pentax France S.A. 12/14, rue Jean Prud'homme, 95100 Argenteuil Cedex, FRANCE  
 Pentax Benelux B.V. (for Netherlands) Spinnveld 25, 4815 HR Breda, NETHERLANDS  
 Jiro Belgium & Luxembourg Weyveldlaan 3-5, 1930 Zaventem, BELGIUM  
 Pentax (Schweiz) AG Industriestrasse 2, 8305 Dietlikon, SWITZERLAND  
 Pentax Scandinavia AB P.O. Box 850, 75127 Uppsala, SWEDEN  
 Pentax Corporation 35 Inverness Drive East, Englewood, Colorado 80112, U.S.A.  
 Pentax Canada Inc. 3131 Universal Drive, Mississauga, Ontario L4X 1E5, CANADA

Printed in Japan

- カメラのソフトケースは使用できません。
- 単3バッテリーパックFcを取り付けるときに、カメラの電池がたに力が加わらないようにご注意ください。
- 単3バッテリーパックFcを取り付けたままでも三脚が使用できます。
- マンガンド電池および、充電用のニッカド電池は使用できません。

### 主な仕様

使用カメラ……MZ-5・MZ-10・MZ-50・MZ-3  
 使用電池……単3乾電池4本使用（アルカリ乾電池[LR6]）  
 大きさ……134.5[幅]×84.5[高]×45[厚]mm  
 質量[重さ]……92g[電池別]

### 撮影可能フィルム本数およびバルブ時間

カッコ内はMZ-50の値です。

一般撮影	約200(180)本
ストロボ撮影[使用率50%]	約35(40)本
ストロボ撮影[使用率100%]	約20(15)本
バルブ露出時間	約18時間

新品のアルカリ乾電池で、当社試験条件による。  
 [24枚撮りフィルム、常温]

### SPECIFICATIONS

Usable camera: MZ-5/ZX-5, MZ-10/ZX-10, MZ-50/ZX-50  
 Power source: Four 1.5 V AA-size Alkaline Batteries  
 Dimensions: 134.5(W) x 84.5(H) x 45(D)mm (5.3" x 3.3" x 1.8")  
 Weight: 92g (3.2 oz) without batteries

### Battery Life (Using 24-exposure film rolls)

General existing light photography	about 200 (180)rolls
Flash photography (using flash 50% of the time)	about 35 (40)rolls
Flash photography (using flash 100% of the time)	about 20 (15)rolls
Bulb exposure time	about 18 hours

\* Figures in ( ) are for MZ/ZX-50.

The batteries were used under Pentax testing conditions. Actual battery life/performance may vary depending on the battery brand, usage of Autofocus, and external conditions such as temperature and freshness of the batteries.

SPECIFICATIONS ARE SUBJECT TO CHANGE AT ANY TIME WITHOUT NOTIFICATION OR ANY OBLIGATION ON THE PART OF THE MANUFACTURER.



旭光学工業株式会社  
 〒174 東京都板橋区前野町2-36-9  
 ペンタックス販売株式会社  
 〒100 東京都千代田区永田町1-11-1

### ●お問い合わせは次の各サービス窓口へ

ペンタックスフォーラム	〒163-04 東京都新宿区西新宿2-1-1 新宿三井ビル1階 (池袋店)	☎03(3348)2941(代)
旭光学 東京サービスセンター	〒104 東京都中央区銀座西8-10 (池袋支店交番並び)	☎03(3671)5621(代)
札幌サービスセンター	〒960 札幌市中央区北10条西18-36 ペンタックス札幌ビル4階	☎011(812)3231(代)
仙台サービスセンター	〒981-11 仙台市東区東1-7-1 平代田生生命中央駅前ビル5階	☎022(374)9683(代)
新潟サービスセンター	〒951 新潟市本町通7番地1153 新潟本町通ビル4階	☎025(224)8391(代)
横浜サービスセンター	〒231 横浜市中区不老町1-6-9 横浜エクスプレントマビル3階	☎045(681)8771(代)
静岡サービスセンター	〒420 静岡市広尾町24-2 住友建設ビル5階	☎054(255)6308(代)
名古屋サービスセンター	〒461 名古屋市中区東1-19-8	☎052(222)5051(代)
金沢サービスセンター	〒920 金沢市尾張町2-8-23 太陽生命ビル6階	☎076(222)20501(代)
大阪サービスセンター	〒542 大阪市中央区南船場1-17-9 /パールビル2階	☎06(271)7996(代)
広島サービスセンター	〒733 広島市西区南観音3-5-2 空通通りビル6階	☎082(234)5681(代)
福岡サービスセンター	〒810 福岡市博多区中洲中馬町3-8 /1ビル1階	☎092(281)6668(代)
お客様相談室	〒104 東京都中央区銀座西8-10 (池袋支店交番並び)	☎03(3672)6479

※日曜・祝日および土曜日は原則として休みます。  
 ただし、年末年始を除きペンタックスフォーラムは年中無休です。